


मुंबई गृहनिर्माण व क्षेत्रविकास मंडळ


(म्हाडाचा घटक)

MUMBAI HOUSING AND AREA DEVELOPMENT BOARD

(A MHADA UNIT)



म्हाडा
MHADA



उपमुख्य अभियंता/ प्रनिस/ मुंबई मंडळ, कक्ष क्र. ३१८, २ रा मजला, गृहनिर्माण भवन, कलानगर, वांद्रे [पूर्व], मुंबई - ४०००५१

दुरध्वनी क्र: ०२२-६६४०५२०६

ई-मेल: eeppdmbmhada@gmail.com

No.EE/PPD/MB/

/2026

Date:- / / 2026

QUOTATION NOTICE

Quotation for the following work is invited from the registered contractor having atleast 5 years experience by the Executive Engineer/PPD/MB. Blank quotation forms for the same will be issued from 06/10/2026 to 08/10/2026 up to 1.00 pm and sealed quotations will be received by this office in room no.318, 2nd floor, Grihanirman Bhavan, Bandra (East), Mumbai- 400051 on 08/10/2026 up to 3.00 pm for the work mentioned below.


NAME OF WORK: - Quotation for Structural Audit of Grihanirman Bhavan Building, Bandra (East), Mumbai. Approximately Total Area of Building 21300 Sqm.

1. The quotation shall be submitted in sealed cover only.
2. The quotationer shall quote the rates in permanent ink only.
3. The rate shall be quoted excluding of all taxes.
4. The Name of work shall be stated clearly on envelope containing the quotation.
5. The cost of quotation is Rs. Nil.

Executive Engineer
PPD/Mumbai Board

Name of work: Quotation for Structural Audit of Grihanirman Bhavan Building, Bandra (East), Mumbai. Approximately Total Area of Building 21300 Sqm.

Sr.no.	Name of items	Total Amount in Rs.
1	Structural Audit of Grihanirman Bhavan Building, Bandra (East), Mumbai. Approximately Total Area of Building 21300 Sqm.	
A	Preparing Detail Structural Audit report Including	
1	• Introduction • General Information of Building • Visual Inspection • ND Test Results and analysis • Distress Mapping Drawings • Photographs • Conclusion & Recommendation • Standard Repair Methodology (If required) • Preparation of Proforma B in BMC format	
2	Non Destructive and Semi-Destructive Tests	
I	Schmidt hammer test	
II	Ultrasonic Pulse Velocity	
III	Half Cell potential Survey	
IV	Carbonation Test	
V	Cover Meter	
VI	Survey Chemical analysis PH, Chloride, SO3	
VII	Core Compression Test	
B	Preparation of Bill of quantities for repairs/strengthening along with measurement sheet by conducting visual inspection and taking required measurements on site	



**Executive Engineer
PPD/Mumbai Board**